# Weathertzetton Assistance

## Work Order Bid (ID)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/17017UC-0837/1

Work Order Type: Weatherization Audit Name: 17017UC-0837

**CLIENT INFORMATION** 

Client ID: 17017UC-0837

### <u>AGENCY INFORMATION</u>

Agency: Upper Cumberland H R A Agency Phone: (931) 528-1127

Address: 3313 Williams Enterprise Drive Fax:
Cookeville, TN 38506 Email Address:

Agency Contact: Simcox, Tommy Work Phone:

Cell Phone: (931) 510-4384

Email Address:

Company Name & License Number:	
Contractor's Signature:	

#### **COMMENT**

1985 SITE BUILT HOME

	Solid wood slab door with & trim	lock set d	bl	Componen	its			Inspected
WO	PLACE W/WOOD EXTERION OD IS BROKEN IN 2 SPOTS WEATHERIZED			LOSE PROF	PERLY, C	CANT		
				Estimated	<u> </u>		Actual	
# Material / Labo	or Description / Comment	Units	Qty	Unit Cost	Qty Unit Cost Total			
Doors	install door with everything	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Comment CAU INS WE	Infiltration Redctn JLK EXTERIOR OF DR1 TALL 2 DOOR SWEEPS ATHERSTRIP 2 DOORS US JLK 27 WINDOWS	ING SILIC	ONE (	Component		Р		Inspected
			Estimated			Actual		
# Material / Labo	or Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
10 Miscellaneous Supplies	Infiltration Reduction	Each	1					
Other Detail				1				1
			Measur	e Sub Total:			Sub Total:	
							L	

Measure 3 DWH	Tank Insulation			Componen	its			Inspected
Comment								
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
Hot Water     Equipment	DHW Tank Insulation	Each	1					
	R-10 minimum-use bubble wrap							
2 Labor	DHW Tank Insulation	Each	1					
Other Detail								
			Measur	re Sub Total:			Sub Total:	
Field Notes:								

Measure 4 Sto	rm Windows			Componen	<i>ts</i> B2,B6 18,C3		16,A1,A	Inspected
Comment A: 36X	50 (3)							
B: 44X	· ,							
C: 24X								
E: 36X	56 (6))							
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	<b>Unit Cost</b>	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	SqFt	246.4					
	<99 U.Iea. Under 100 UI							
2 Labor	Storm Window	SqFt	246.4					
3 Other	Storm Window	Each Window	18					
	<99 U.I ea Over 100 UI							
Other Detail								
			Measu	re Sub Total:		]	Sub Total:	
Field Notes:								
		Work O	rder Gra	nd Total:		Gran	d Total:	